

# **PRECISION BENCH LATHE**

**OPERATING MANUAL**

**HEALTH AND SAFETY**

**GUIDANCE NOTES**

**MODEL : 11CF - 16CF**

**REVISION : 1**

**DATE OF ISSUE : 7.16.1995**

**FILE NO. : OM-11CF1**

Chapter	Contents	Page
<b>1</b>	<b>OPERATING SAFETY GUIDELINES</b>	<b>1</b>
1.1	OPERATING SAFETY PRECAUTIONS	1
1.2	POTENTIAL OPERATING HAZARDS	1
1.3	GENERAL SAFETY RULES	2
1.4	WARNING SIGNS AND MARKS ON THE MACHINE	5
1.5	SAFETY DEVICES AND INSPECTION	6
<b>2</b>	<b>SUMMARY OF THE MACHINE</b>	<b>7</b>
2.1	BASIC DESCRIPTION OF THE MACHINE AND PART NAMES	7
2.2	DIMENSION AND WORK RANGE OF MACHINE	8
2.3	MACHINE SPECIFICATIONS	8
2.4	OPERATOR POSITION NOISE LEVEL	10
2.5	SPINDLE NOISE AND TALISTOCK QUILL TAPER DRAWING	11
<b>3</b>	<b>PREPARATIONS BEFORE INSTALLING THE MACHINE</b>	<b>12</b>
3.1	FOUNDATION REQUIREMENT	12
3.2	POWER REQUIREMENTS	12
3.3	ENVIRONMENT REQUIREMENT	12
<b>4</b>	<b>TRANSPORT AND INSTALLATION</b>	<b>13</b>
4.1	TRANSPORT	13
4.2	INSTALLATION	13
<b>5</b>	<b>OPERATION</b>	<b>15</b>
5.1	SAFETY INSPECTION BEFORE OPERATION	15
5.2	CONTROL DEVICE LAYOUT	16
5.3	SPINDLE SPEED CHANGE	16
5.4	TO START THE MACHINE	18
5.5	SPINDLE FORWARD-REVERSE SELECTION KNOB	18
5.6	FORWARD - REVERSE SELECTION KNOB	18
5.7	THREADING	18
5.8	HALF NUT CONTROL LEVER	18
5.9	LONGITUDINAL AND CROSS FEED ENGAGEMENT LEVER	18
5.10	THREAD INDICATOR	20
5.11	AUTOMATIC FEEDING	21
5.12	TOOL POST AND SADDLE	21
5.13	TAIL STOCK	21
5.14	COOLANT	21
<b>6</b>	<b>DAILY SERVICE</b>	<b>22</b>
6.1	POSITION OF LUBRICATION AND FILLING DEVICES	22
6.2	DAILY MAINTENANCE FOR OPERATORS	22
<b>7</b>	<b>ADJUSTMENT</b>	<b>23</b>
7.1	LEVEL	23
7.2	MAIN SPINDLE BEARING ADJUSTMENT	23
7.3	ADJUSTMENT OF SADDLE AND CROSS-SLIDE FEED	23
7.4	ADJUSTMENT OF TAPER GIB	23
7.5	CROSS SLIDE NUT	24
7.6	ALIGNMENT OF THE TAILSTOCK	24
7.7	TAILSTOCK LOCKING BOLT ADJUSTMENT	24
7.8	BACKLASH ADJUSTMENT OF SADDLE LEADSCREW	24
7.9	SPARE PARTS	25



# **1 OPERATING SAFETY GUIDELINES**

## **1.1 OPERATING SAFETY PRECAUTIONS**

- a. THE OPERATOR MUST BE A TECHNICIAN WHO IS TRAINED IN THE OPERATION HE SHOULD HOLD THE QUALIFICATION OF CERTIFICATED LATHE OPERATOR OF A CONVENTIONAL LATHE & FAMILIAR WITH THE MANUAL.
- b. THE OPERATOR SHOULD WEAR SAFETY CLOTHES, SUCH AS A HELMET, SAFETY GLASSES WORKING CLOTHES, SAFETY SHOES ..... ETC, WHICH MUST CONFORM WITH LOCAL INDUSTRIAL SAFETY REGULATIONS.
- c. KEEP THE MACHINE AND WORK AREA NEAT, CLEAN AND TIDY.
- d. KEEP ALL GUARDS AND COVER PLATES IN PLACE AND ALL MACHINE CABINET DOORS CLOSED.
- e. NEVER LAY ANYTHING ON THE WORKING SURFACES OF THE MACHINE, WHERE IT MAY FOUL ROTATING OR MOVING PARTS.
- f. DO NOT TOUCH OR REACH OVER MOVING OR ROTATING MACHINE PARTS.
- g. ENSURE YOU KNOW HOW TO STOP THE MACHINE BEFORE STARTING IT.
- h. DO NOT OPERATE THE MACHINE IN EXCESS OF ITS RATED CAPACITY.
- i. DO NOT WEAR RINGS, WATCHES, TIES OR LOOSE SLEEVED CLOTHING.
- j. STOP THE MACHINE IMMEDIATELY IF ANYTHING UNEXPECTED HAPPENS.
- k. DO NOT INTERCHANGE CHUCKS OR OTHER SPINDLE MOUNTING ITEMS WITHOUT CHECKING FOR CORRECT LOCKING AND MAXIMUM SPEED RATING.
- l. CHECK THE LOAD CAPACITY OF REVOLVING CENTRES FOR THE CURRENT APPLICATION.
- m. ISOLATE THE MACHINE WHEN LEAVING IT UNATTENDED.
- n. THE USE OF FLUID CAUSING POISONING OR CORROSION WHILE CUTTINGS PROHIBITED.
- o. DO NOT CUTTING MAGNESIUM METAL OR HIGH MAGNESIUM ALLOYS OR ANY OTHER MATERIAL WHICH MAY GENERATE FLAMMABLE HAZARDS.

## **1.2 OPERATING POTENTIAL HAZARDS**

### **SAFE OPERATION OF LATHE CHUCKS**

WHERE DETAILS OF OPERATING SPEEDS AND OF MAXIMUM RECOMMENDED OPERATING SPEEDS ARE SUPPLIED THESE ARE INTENDED ONLY AS A GUIDE. SUCH DETAILS MUST BE REGARDED AS FOR GENERAL GUIDANCE ONLY.

DO NOT USE DAMAGED CHUCKS.

THE GRIPPING POWER REQUIRED FOR ANY GIVEN APPLICATION IS NOT KNOWN IN ADVANCE SO THAT CARE WHEN SELECTING AN APPROPRIATE CHUCK..

THE ACTUAL GRIPPING POWER BEING USED FOR ANY GIVEN APPLICATION IS NOT KNOWN BY THE CHUCK MANUFACTURER.

THERE IS THE POSSIBILITY OF THE WORK PIECE BECOMING INSECURELY GRIPPED DUE TO THE INFLUENCE OF CENTRIFUGAL FORCE UNDER CERTAIN CONDITIONS. THE FACTORS INVOLVED INCLUDE:

- a. TOO HIGH A SPEED FOR A PARTICULAR APPLICATION.
- b. WEIGHT AND TYPE OF GRIPPING JAWS IF NON-STANDARD.

- c. RADIUS AT WHICH GRIPPING JAWS ARE OPERATING IS INCORRECT.
- d. CONDITION OF CHUCK IS INADEQUATE LUBRICATED.
- e. THE STATE OF BALANCE IS NOT CORRECT.
- f. THE GRIPPING FORCE APPLIED TO THE WORK PIECE IN THE STATIC CONDITION IS INADEQUATE.
- g. MAGNITUDE OF THE CUTTING FORCES INVOLVED ARE TOO GREAT.
- h. THE WORK PIECE IS GRIPPED INCORRECTLY.

CAREFUL ATTENTION MUST BE PAID TO THESE FACTORS. AS THEY VARY WITH EACH PARTICULAR APPLICATION, A MANUFACTURER CANNOT PROVIDE SPECIFIC FIGURES FOR GENERAL USE, THE FACTORS INVOLVED BEING OUTSIDE HIS CONTROL.

### **1.3 GENERAL SAFETY RULES**

- (1) DO NOT GRIP A COMPONENT WITH GREASE OR OIL ON IT.

GRIP ALL COMPONENTS FIRMLY.

DO NOT ATTEMPT TO HOLD COMPONENTS THAT ARE TOO AWKWARD OR TOO DIFFICULT TO HOLD .

DO NOT HOLD COMPONENTS THAT ARE TOO HEAVY FOR THE MACHINE.

KNOW HOW TO HOLD COMPONENTS PROPERLY WHEN LIFTING.

- (2) BE SURE TO CLEAN OIL OR GREASE FROM HAND TOOLS, LEVERS AND HANDLES.

BE SURE THERE IS ENOUGH ROUGHNESS ON THE SURFACE OF THE HAND TOOL OR LEVER HANDLE FOR PROPER SAFE HAND CONTACT.

- (3) GRIP HAND TOOLS AND LEVER HANDLES FIRMLY.

ALWAYS CHOOSE THE PROPER HAND TOOL AND APPROPRIATE GRIP POSITION ON THE LEVER HANDLE.

DO NOT USE HAND TOOLS OR LEVER HANDLES IN AN AWKWARD POSITION.

DO NOT APPLY EXCESSIVE FORCE.

- (4) DO NOT ALLOW TURNING OR HAND TOOLS TO BE CAUGHT IN THE CHUCK OR OTHER HOLDING DEVICE.

- ✓(5) DO NOT USE BROKEN, CHIPPED OR DEFECTIVE TOOLS.

- ✓(6) BE SURE WORK PIECE CANNOT MOVE IN CHUCK OR OTHER HOLDING DEVICE.

- (7) BEWARE OF IRREGULAR SHAPED WORK PIECES.

- (8) BEWARE OF LARGE BURRS ON WORK PIECES.

- (9) ALWAYS SELECT THE CORRECT TOOL FOR THE JOB.

- (10) DO NOT RUN THE MACHINE UNATTENDED.

- (11) DO NOT USE TOOLS WITHOUT HANDLES.

- ✓(12) ALWAYS SUPPORT THE WORK PIECE AS NECESSARY USING CHUCKS, STEADIES AND CENTERS.

- (13) CORRECTLY LOCATE TOOL IN SOCKET HEADS AND SCREW SLOTS.

- (14) BEWARE OF OBSTRUCTIONS THAT PREVENT COMPLETELY TIGHTENING THE SCREWS - ENSURE SCREW IS TIGHT.
- (15) DO NOT RUSH WORK.
- (16) NEVER SUBSTITUTE THE WRONG SIZE TOOLS IF THE CORRECT SIZED TOOL IS NOT AVAILABLE OR CANNOT BE LOCATED IN THE SHOP.
- (17) DO NOT MOVE GUARDS WHILE LATHE IS UNDER POWER.
- (18) DO NOT PLACE HAND OR BODY IN PATH OF MOVING OBJECTS.

BEWARE OF MOVING LATHE PARTS THAT CAN FALL.

BEWARE OF WHERE YOU ARE MOVING YOUR HAND OR BODY IN RELATIONSHIP TO THE LATHE.

BEWARE OF HOLDING A TOOL OR OTHER PARTS INSERTED IN OR ATTACHED TO THE CHUCK OR WORK PIECE.

BEWARE OF HANDS OR OTHER PARTS OF THE BODY THAT MAY IN POSITION TO BE HIT BY A CHUCK OR WORK PIECE.

- (19) BEWARE OF ACCIDENTALLY MOVING LEVERS, CLUTCHES (WHERE APPLICABLE) OR TURNING THE POWER ON.
- (20) KNOW THE FUNCTION OF EACH AND EVERY CONTROL.
- (21) NEVER PLACE HAND ON CHUCK OR WORK PIECE TO STOP ROTATION OF THE SPINDLE.
- (22) ON MACHINES WITH CLUTCH DRIVE MAKE SURE CLUTCH IS COMPLETELY DISENGAGED ON STOOPING, AND KEPT PROPERLY ADJUSTED.
- (23) MAKE SURE POWER HAS BEEN TURNED OFF WHEN LATHE IS UNUSED FOR SOMETIME.
- (24) ALLOW CHUCK TO STOP BEFORE ADJUSTING,
- (25) DO NOT ALLOW DISTRACTIONS TO INTERFERE WITH LATHE OPERATIONS.

DO NOT OPERATE LATHE WHILST TALKING.

- (26) BEWARE OF LATHE DANGERS WHEN ATTENDING TO OTHER ASPECTS OF LATHE OPERATION. E.G. WHILST OPERATING TAILSTOCK.
  - (27) BEWARE OF LOOSE CLOTHING NEAR THE ROTATING PARTS OF THE LATHE.
  - (28) BEWARE OF LOOSE HAIR NEAR THE ROTATING PARTS OF THE LATHE.
  - (29) BEWARE OF PERFORMING ANOTHER OPERATION WHILE IN CLOSE PROXIMITY TO ROTATING PARTS ON THE LATHE.
  - (30) ENSURE FILING AND DEBURRING OPERATIONS ARE COMPLETED AWAY FROM THE LATHE.
  - (31) BE SURE CLUTCH IS IN NEUTRAL POSITION WHEN PLACING GAUGES ON COMPONENTS GRIPPED IN THE CHUCK.
  - (32) BE SURE MOTOR IS NOT RUNNING WHEN USING GAUGES ON THE MACHINE.
  - (33) ALWAYS WEAR THE APPROPRIATE PROTECTION BEFORE OPERATING THE LATHE.
- ALWAYS WEAR THE CORRECT PROTECTION BEFORE OPERATING THE LATHE.

NEVER REMOVE PROTECTION FOR EVEN A SHORT TIME WHEN OPERATING THE LATHE.

WEAR PROTECTIVE DEVICES CORRECTLY.

KNOW THE CORRECT WAY TO WEAR PROTECTIVE DEVICES.

(34) BEWARE OF SWarf AND CHIPS FLYING FROM THE LATHE.

(35) KEEP PROTECTIVE GUARDS AT THE POINT OF OPERATION.

(36) a) WHEN THE CHUCK AND WORK PIECE ARE IN MOTION NEVER REACH OVER, UNDER OR AROUND A WORK PIECE TO MAKE AN ADJUSTMENT.

b) NEVER REACH OVER, UNDER OR AROUND A WORK PIECE RETRIEVE ANYTHING.

c) BEWARE OF WHERE YOU LEAVE YOUR TOOLS DURING SET UP.

d) NEVER REACH OVER, UNDER OR AROUND THE WORK PIECE TO MOVE HAND TOOLS TO ANOTHER .

e) NEVER REACH OVER, UNDER OR AROUND THE WORK PIECE TO TIGHTEN SCREWS ETC.

f) NEVER REACH OVER, UNDER OR AROUND WORK PIECE TO REMOVE SWarf.

(38) KNOW THE PROPER PROCEDURE FOR APPLYING FORCE.

NEVER APPLY FORCE FROM AN AWKWARD POSITION.

(39) NEVER MOUNT A WORK PIECE TOO LARGE FOR THE LATHE.

(40) USE THE CORRECT LIFTING EQUIPMENT NECESSARY FOR HANDLING WORK PIECES.

(41) NEVER APPLY UNDUE FORCE ON HANDLES OR LEVERS.

(42) SECURE ALL WORK PIECES.

(43) SECURE ALL JAWS, NUTS, BOLTS AND LOCKS.

(44) ALWAYS USE THE CORRECT EQUIPMENT.

(45) NEVER TAKE DEPTH OF CUTS BEYOND MACHINE'S CAPABILITY.

NEVER USE EXCESSIVE FEED RATES.

(46) NEVER USE EXCESSIVE FORCE IN POLISHING, FILING AND DEBURRING.

(47) ALWAYS USE THE PROPER HAND TOOL TO REMOVE SWarf.

NEVER HURRY WHEN REMOVING SWarf.

BEWARE OF SWarf WRAPPED AROUND THE CHUCK OR WORK PIECE.

(48) BEWARE OF TOOL/LATHE PARTS FALLING ONTO CONTROLS.

(49) ONLY USE T-WRENCH WHEN LOCKING WORKPIECE.

(50) DO NOT APPLY CHISELS OR EMERY PAPER BY HAND TO THE WORKPIECE.

## 1.4 WARNING SIGN AND MARKS ON THE MACHINE




FIG.1


1

MODEL:	_____
SERIAL NO.:	_____
DATE:	_____
MADE IN TAIWAN, R.O.C.	


MACHINE IDENTIFICATION.




DO NOT MOVE SPEED RANGE SELECTOR KNOB WHILST THE SPINDLE IS ROTATING.



SWITCH OFF THE POWER BEFORE OPENING THE SIDE COVER.



CE MARK.



DO NOT TOUCH TOOLING, CHUCK OR WORKPIECE WHEN SPINDLE IS REVOLVING.




ELECTRICITY AREA.



AUTOMATIC FEED DIRECTION INDICATE.




8




**GROUND AND HARDENED BED  
LABEL.**

9



**THE LENGTH OF WORK PIECE  
CAN NOT BE OVER 500mm, FROM  
THE END COVER.**

### 1.5 SAFETY DEVICE AND INSPECT



1. EMERGENCY STOP BUTTON

2. CHUCK GUARD

3. LEADSCREW & FEED ROD PROTECTION COVER

4. FOOT BRAKE PEDAL

(1) AFTER STEP ON THE FOOT BRAKE PEDAL, THE SPINDLE WILL STOP ROTATING AND POWER WILL BE OFF.

(2) THE SPINDLE WILL ROTATE, AFTER SWITCH "FORWARD & REVERSE LEVER" TO MIDDLE POSITION AND RESTART THE POWER.

5. CARRIAGE GUARD

INSPECT BEFORE OPERATING

1. THE POWER WILL BE OFF AND SPINDLE STOP, WHEN PRESS EMERGENCY STOP BUTTON.

2. THE POWER WILL BE OFF AND SPINDLE WILL NOT ROTATE WHEN CHUCK GUARD IS LIFTED.

3. AFTER STEP ON THE FOOT BRAKE PEDEL, THE SPINDLE WILL STOP RETAINING IMMEDIATELY AND POWER WILL BE OFF.

## 2 SUMMARY OF THE MACHINE

### 2.1 BASIC DESCRIPTION OF THE MACHINE AND PART NAMES




FIG. 3

#### 1. HEADSTOCK

THE HEADSTOCK IS A ONE-PIECE SPECIAL (FC-25) CAST IRON CASTING FITTED WITH ADJUSTING SCREWS FOR PROPER ALIGNMENT TO THE BEDWAYS AND FASTENED TO THE BED WITH SIX SCREWS. THE SPINDLE IS SUPPORTED ON TWO TAPER ROLLER BEARINGS FOR MAXIMUM RIGIDITY AND PRECISION, AND THE OTHER GEARS SHAFTS OPERATE ON BALL BEARINGS. THE COMPLETE GEAR TRAIN THE SELF LUBRICATED BY SPLASH SYSTEM.

#### 2. BED AND FLOOR STAND

THE BED IS MADE OF SPECIAL CAST IRON (FC-25) IN ONE-PIECE CASTING AND HAS A BOX-SECTION MEMBER. THE BEDWAYS IS PRECISION GROUND AND HAS BEEN SUBJECTED TO HIGH FREQUENCY HEAT-TREATMENT (HRC 55).

THE FLOOR STAND IS SEPARATED FROM THE BED. THE FLOOR STAND IS READY TO REMOVE, DISENGAGE AND REFIT, THERE ARE 6 SETS OF SCREW TO ADJUST THE MACHINE LEVEL.

#### 3. SADDLE

THE WIDE SADDLE INSURES MAXIMUM RIGIDITY AGAINST STRESSES OF HEAVY CUTTING LOADS.

THE CROSS-SLIDE AND COMPOUND SLIDES ARE FITTED TO THE SADDLE.

WHEN FITTED WITH INCH SCREW, THE CROSS SLIDE MOVES .200" ON DIAMETER FOR EACH REVOLUTION OF THE HAND WHEEL AND THE DIAL IS GRADUATED IN .001". THE TRAVEL OF THE CROSS SLIDE IS 172MM (6-3/4"). THE COMPOUND SLIDE TRAVEL IS 92MM (3-5/8").

#### 4. APRON

THE APRON IS A HEAVY DUTY DOUBLE WALL CASTING AND ALL THE SHAFTS AND GEARS ARE SUPPORTED AT BOTH ENDS. IT CONTAINS ALL THE NECESSARY GEARING AND CONTROLS TO TRANSMIT POWER FEED FOR LONGITUDINAL AND CROSS MOVEMENTS AS WELL AS FOR THREAD CUTTING. THE CONTROLS ARE INTERLOCKED TO PREVENT SIMULTANEOUS ENGAGEMENT OF THE FEEDS AND THREADING.

## 5. GEAR BOX


THIS GEAR BOX ALLOWS SELECTION OF METRIC AND INCH THREADS AS WELL AS FEEDS.

## 6. TAILSTOCK

THE TAILSTOCK IS ALSO MADE OF CAST IRON (FC 25) RUGGED AND COMPACT. IT IS EASY TO MOVE AND ADJUST. IT CAN BE KEPT CLOSE TO THE HEAD STOCK WITHOUT THE INTERFERENCE FOR THE OPERATION OF TOOL POST.

THE LATHE IS MANUFACTURED TO JIS STANDARDS AND ALL SLIDING SURFACES ARE PRECISION GROUND.

### 2.2 DIMENSION AND WORK RANGE OF MACHINE



### 2.3 MACHINE SPECIFICATIONS

#### 2.3.1 SPECIFICATION

ITEM	SPECIFICATION
SWING OVER BED	339MM (13-3/8")
SWING OVER SADDLE	188MM (7-3/8")
SWING OVER GAP	464MM (18-1/4")
DISTANCE BETWEEN CENTERS	11CF 610MM (24") 16CF 915MM (36")
WIDE OF BED	195MM (7-11/16")
HOLE THROUGH SPINDLE	38.5MM (1-1/2")
TAPER IN SPINDLE NOSE BUSH	M.T. #5
TAPER IN TAILSTOCK BARREL	M.T. #3
NUMBER OF SPINDLE SPEEDS	12
RANGE OF SPINDLE SPEEDS	40-1500 R.P.M.
TOTAL TRAVEL OF TOP SLIDE	92MM (3-5/8")
TOTAL TRAVEL OF CROSS SLIDE	172MM (6-3/4")
TOTAL TRAVEL OF TAILSTOCK BARREL	102MM (4")
NUMBER OF METRIC PITCHES	22 (INCH LEADSCREW) / 27 (METRIC LEADSCREW)
RANGE OF METRIC PITCHES	0.2-0.75MM
NUMBER OF INCH THREADS	40
RANGE OF INCH THREADS	4-112 T.P.I.
LEAD SCREW DIAMETER & PITCHES	7/8" (22MM) X 8 T.P.I. OR PITCH 3MM

RANGE OF CROSS FEEDS	0.007MM-0.202MM (0.0003"-0.0081")
RANGE OF LONGITUDINAL FEEDS	0.042MM-1.188MM (0.0017"-0.047")
MOTOR HORSE POWER	1-1/2HP
NET WEIGHT	11CF 400 KGS. / 16CF 460 KGS
MEASUREMENT	11CF193X73.5X134cm / 16CF 229X73.5X134 CM

### 2.3.2 STANDARD ACCESSORIES

1. THREAD CUTTING INDICATOR	1 PC.
2. CENTER SLEEVE (M.T. #5)	1 PC.
3. CENTER (M.T. #3)	2 PC.
4. TOOL POST WRENCH	1 PC.
5. METRIC CHANGE GEAR	1 SET.
6. BACKING PLATE	1 PC.
7. 4-WAYS TOOL POST	1 PC.
8. TOOL BOX & TOOL KITS	1 SET.
9. CHIP TRAY	1 PC.
10. MOTOR PULLEY & BELT	1 SET.
11. 3-JAW SCROLL CHUCK 6"	1 PC.
12. ELECTRIC MOTOR 3HP (3PH)	1 PC.
13. COOLANT PUMP & FITTINGS	1 SET.
14. FULL LENGTH SPLASH GUARD	1 PC.
15. CHUCK GUARD	1 PC.
16. FLOOR STAND	1 PC.
17. FOOT BRAKING EQUIPMENT	1 SET.
18. LEAD SCREW COVER	1 SET.

### 2.3.3 SPECIAL ACCESSORIES :

1. STEADY REST	1 PC.
2. FOLLOW REST	1 PC.
3. CAMLOCK FACE PLATE (10" OR 12")	1 PC.
4. 4-JAW INDEPENDENT CHUCK 8"	1 PC.
5. ELECTRIC MOTOR 2HP ( 1ph OR 3ph )	1 PC.
6. DRILL CHUCK 1/2".	1 PC.
7. ROLLING CENTER MT#3.	1 PC.
8. SINGLE TOOL POST	1 PC.
9. MICROMETER TYPE CARRIAGE STOP	1 PC.
10. 4-POSITION CROSS SLIDE STOP	1 PC.
11. MACHINE LIGHT	1 PC.
12. MILLING ATTACHMENT	1 PC.
13. QUICK CHANGE TOOL POST	1 SET.
14. CAMLOCK BACKING PLATE.	1 PC.
15. 5C HAND WHEEL COLLECT CLOSER.	1PC.
16. 5C LEVER COLLECT CLOSER.	1PC.
17. TAPER ATTACHMENT.	1SET.

## 2.4 OPERATOR POSITION AND NOISE LEVEL




Fig. 4

**NOISE LEVEL : LESS THAN 80 dB**

**IT A DISTANCE OF 1 METER FROM THE SURFACE OF THE MACHINERY AND AT A HEIGHT OF 1.6 METER FROM FLOOR.**






Fig. 5

### 2.5.1 SPINDLE NOISE DETAIL



### 3 PREPARATIONS BEFORE INSTALLING THE MACHINE

#### 3.1 FOUNDATION REQUIREMENT



#### 3.2 POWER REQUIREMENTS

VOLTAGE	STEADY STATE VOLTAGE 0,9 ... 1,1 OF NOMINAL VOLTAGE.
FREQUENCY	0,99 ... 1,01 OF NORMAL FREQUENCY CONTINUOUSLY, 0,98 ... 1,02 SHORT-TIME.
HARMONICS	HARMONIC DISTORTION NOT TO EXCEED 10% OF THE TOTAL r.m.s. VOLTAGE BETWEEN THE LIVE CONDUCTORS FOR THE SUM OF THE 2nd THROUGH 5th HARMONIC.
VOLTAGE UNBALANCE IN 3-PHASE SUPPLIES	NEITHER THE VOLTAGE OF THE NEGATIVE SEQUENCE COMPONENT NOR THE VOLTAGE OF THE ZERO SEQUENCE COMPONENT SHALL EXCEED 2% OF THE POSITIVE SEQUENCE COMPONENT.
VOLTAGE IMPULSES	NOT TO EXCEED 1,5 MS IN DURATION WITH A RISE / FALL TIME BETWEEN 500 NS AND 500 $\mu$ s AND A PEAK VALUE NOT MORE THAN 200% OF THE RATED r.m.s. SUPPLY VOLTAGE.
VOLTAGE INTERRUPTION	SUPPLY INTERRUPTED OR AT ZERO VOLTAGE FOR NOT MORE THAN 3 ms AT ANY RANDOM TIME IN THE SUPPLY CYCLE. THERE SHALL BE MORE THAN 1 S BETWEEN SUCCESSIVE INTERRUPTIONS.
VOLTAGE DIPS	VOLTAGE DIPS SHALL NOT EXCEED 20 % OF THE PEAK VOLTAGE OF THE SUPPLY FOR MORE THAN ONE CYCLE. THERE SHALL BE MORE THAN 1 S BETWEEN SUCCESSIVE DIPS.

#### 3.3 ENVIRONMENT

3.3.1 TEMPERATURE : NORMAL TEMPERATURE WITHIN +10 °C TO 38 °C.

3.3.2 HUMIDITY : 30% TO 95% .

3.3.3 KEEP AWAY FROM GAS, CHEMICAL, OR EXPLOSIVE STAFF.

3.3.4 KEEP AWAY FROM ELECTRICAL MAGNETIC INTERFERENCE.

3.3.5 OTHERS: KEEP AWAY FROM ASHES, ACID, OR SALTY AREA.



## 4 TRANSPORT AND INSTALLATION

### 4.1 TRANSPORT

#### 4.1.1 MACHINE WEIGHT

THE WEIGHT OF 18DF LATHE IS : 550 KGS

**ALWAYS ENSURE CAPACITY OF EQUIPMENT IS ADEQUATE BEFORE ATTEMPTING TO LIFT.**

#### 4.1.2 PREPARATION AND SAFETY CHECKS


1. REMOVE ALL ITEMS OF LOOSE EQUIPMENT .
2. CLAMP TAIL STOCK SECURELY AT THE TAIL OF THE BED.
3. CLAMP SADDLE TO BED.
4. ENSURE EYEBOLTS, SHACKLE PINS AND SECURING SCREWS OF LIFTING EQUIPMENT ARE  
→ CORRECTLY TIGHTENED.
5. ONLY USE THE CORRECT EQUIPMENT SUPPLIED.

#### 4.1.3 LIFTING

1. SLIDE THE CARRIAGE NEAR TO HEADSTOCK (FIG. 6 -1).
2. LET CABLE THROUGH THE HANGER (FIG. 6-B), THE OTHER SIDE OF CABLE IS HOOKED UP. (FIG. 6-2)
3. CAREFULLY LIFT THE LATHE CLEAR OF GROUND AND IF NECESSARY REPOSITION THE SADDLE TO ACHIEVE BALANCE BEFORE LIFTING FURTHER.

**NOTE : a. THE CABLE SHOULD TAKE THE WEIGHT AT LEAST 1 TON.**

**b. TAKING SOME PROTECTIONS (CLOTH OR CARD BOARD) ON SIDE COVER. (FIG. 6-3)**



## **4.2 INSTALLATION**

### **4.2.1 CLEANING**

ALL MACHINE SURFACES ARE COVERED WITH A ANTI RUST PRESERVATIVE WHICH MUST BE THOROUGHLY CLEANED OFF BEFORE MOVING ANY PARTS OF THE LATHE. ONLY MILD SOLVENT AND SOFT RAGS MUST BE USED FOR CLEANING.

**NOTE: 1. SPECIAL CARE MUST BE TAKEN TO COMPLETELY CLEAN THE LEAD SCREW, FEED SHAFT, RACK AND PINION.**

**2. NEVER USE LACQUER, THINNER, GASOLINE OR OTHER INFLAMMABLE LIQUIDS AS A CLEANING FLUID.**

### **4.2.2 LEVEL ADJUSTMENT**

- 1. IT IS MOST IMPORTANT TO SET THE LATHE LEVEL AND FIRM IN ORDER TO PERFORM ACCURATELY. FOR A BEST RESULT, IT IS SUGGESTED TO MOUNT THE LATHE ON A CONCRETE FLOOR.**
- 2. IF THE MACHINE CAN NOT BE ANCHORED TO A CONCRETE FLOOR IT IS RECOMMENDED TO INSTALL THE LATHE ON A HEAVY STEEL PLATE FITTED WITH LEVELING SCREWS SO AS TO PROPERLY ALIGN AND LEVEL THE MACHINE.**
- 3. IF THE LATHE IS TO BE MOUNTED ON A BENCH, FIRST MAKE SURE THAT THE BENCH, IS PROPERLY LEVELED TO THE REQUIRED TOLERANCE.**

### **4.2.3 ELECTRICAL CONNECTIONS**

THE ELECTRICAL EQUIPMENT SUPPLIED IS DIFFERENT DEPENDING ON THE MODELS AND YOUR REQUIREMENTS. THE MACHINE IS READY FOR INSTALLATION ON 3 PHASE OR SINGLE PHASE, 50 OR 60 CYCLES, AC. VOLTAGE AS YOU REQUIRE.

**NOTE: 1. BEFORE CONNECTING TO A POWER SOURCE ESTABLISH MOTOR VOLTAGE, PHASE AND CYCLES.**

**2. MADE SURE THAT POWER SUPPLY IS PROPERLY FUSED AND GROUNDED.**

**3. MOTOR ROTATION MUST BE CLOCKWISE WHEN VIEWED FROM THE PULLEY END. IF THE MOTOR TURNS IN THE WRONG DIRECTION INTERCHANGE THE PHASES FOR CORRECTION.**

### **4.2.4 CHUCK MOUNTING**

WHEN FITTING CHUCKS OR FACEPLATES, FIRST ENSURE THAT THE SPINDLE NOSE AND CHUCK TAPERS ARE CLEAN; MOUNT THE CHUCK AND ASCERTAIN THAT THE CAMS LOCK IN THE CORRECT POSITION. WHEN MOUNTING A NEW CHUCK IT MAY BE NECESSARY TO RESET THE CAMLOCK STUDS (A). TO DO THIS, REMOVE THE CAPHEAD LOCKING SCREWS (B) AND SET EACH STUD SO THAT THE SCRIBED RING (C) IS FLUSH WITH THE REAR FACE OF THE CHUCK AND WITH THE CIRCULAR SCALLOP IN LINE WITH THE LOCKING SCREW HOLE MAKE SURE THE RATED MAX. RPM OF THE CHUCK IS SUITABLE (SEE INSET).


NOW REMOUNT THE CHUCK OR FACEPLATE ON THE SPINDLE NOSE AND TIGHTEN THE SIX CAMS IN TURN. WHEN CORRECTLY TIGHTENED THE CAMLOCK LINE ON EACH CAM SHOULD BE BETWEEN THE TWO "V" MARKS ON THE SPINDLE NOSE.

IF ANY OF THE CAMS DO NOT TIGHTEN FULLY WITHIN THESE MARKS, REMOVE THE CHUCK OF FACEPLATE AND RE-ADJUST THE STUD AS INDICATED IN THE DIAGRAM.

ONCE A CHUCK HAS BEEN CORRECTLY FITTED IT MAY BE STAMPED TO ALIGN WITH THE SPINDLE REFERENCE MARK FOR SUBSEQUENT RE-MOUNTING IN THE SAME POSITION.

## WARNING

1. ONLY HIGH SPEED CHUCKS TO BE USED THIS MACHINE. (MAX. 2000RPM)



## **5 OPERATION**

### **5.1 SAFETY INSPECTION BEFORE OPERATION**

BEFORE ATTEMPTING TO START THE MACHINE READ CAREFULLY THE LATHE OPERATING INSTRUCTIONS IN THIS MANUAL.

#### **LATHE SAFETY**

IN THE INTERESTS OF SAFETY PLEASE READ SECTION 1.1, 1.2 AND 1.3 AT THE BEGINNING OF THIS MANUAL.  
SOME OF THE KEY POINTS ARE:

1. ENSURE YOU KNOW HOW TO STOP THE MACHINE BEFORE STARTING IT.
2. STOP MACHINE IMMEDIATELY ANYTHING UNEXPECTED HAPPENS.
3. ENSURE SPEEDS, FEEDS AND DEPTHS OF CUT ARE COMPATIBLE WITH THE COMPONENT AND THE HOLDING DEVICES.
4. DO NOT TOUCH TOOLING, CHUCK OR WORK PIECE WHEN SPINDLE IS REVOLVING.
5. WEAR AND UTILIZE SUITABLE PROTECTIVE CLOTHING AND EQUIPMENT.

## 5.2 CONTROL DEVICE LAYOUT




FIG. 6

- |   |   |
|---|---|
| 01. SWITCH                              | 14 HAND WHEEL FOR TAIL STOCK QUILL            |
| 02. COOLANT PUMP ON/OFF SWITCH          | 15. TAILSTOCK SET OVER SCREW                  |
| 03. DISPLAY LIGHT                       | 16. SPINDLE FORWARD AND REVERSE CONTROL LEVER |
| 04. HIGH/LOW SPEEDS CHANGE KNOB         | 17. LEADSCREW NUT ENGAGEMENT LEVER            |
| 05. EMERGENCY STOP BUTTONS              | 18. CROSS/LONGITUDINAL FEED LEVER             |
| 06. JOGGING BUTTONS                     | 19. HAND WHEEL FOR LONGITUDINAL FEEDS         |
| 07. CHUCK GUARD                         | 20. FOOT BRAKE                                |
| 08. BACKING PLATE                       | 21. FEEDS & THREADS SELECTIVE KNOB            |
| 09. CARRIAGE GUARD                      | 22. GEAR BOX SHIFT LEVER                      |
| 10. LOCKING BOLTS                       | 23. GEAR BOX SHIFT LEVER                      |
| 11. CLAMPING LEVER FOR SQUARE TOOL POST | 24. SIDE COVER                                |
| 12. TOOL SLIDE HANDLE                   | 25. POSITIVE - REVERSE SELECTIVE KNOB         |
| 13. TAILSTOCK CLAMPING LEVER            |   |

### TO STOP THE MACHINE

- (1) RETURN THE SPINDLE CONTROL LEVER TO THE NEUTRAL POSITION. (15 IN FIG., 6)
- (2) PRESS EMERGENCY TO STOP. (5 IN FIG. 6)
- (3) SWITCH OFF THE KEYSWITCH. (4 IN FIG. 6)
- (4) SWITCH MAIN ISOLATR OFF.

## 5.3 SPINDLE SPEED CHANGE

### SPEED SELECTION

12 SPINDLE SPEEDS ARE POSSIBLE BY THE PROPER THREE GEAR SELECTIONS (2 FIG. 7) AND THE HIGH-LOW LEVER (1 IN FIG. 7) IN TWO MOTOR PULLEY RANGES.




FIG. 7.

POSITION	SPEED	R P M
D PULLEY	L	40
		80
		150
	H	290
		565
		1080
d PULLEY	L	55
		110
		210
	H	405
		785
		1500

**NOTE: WHEN MESH THE INTERMEDIATE GEAR WITH SPINDLE GEAR, OPERATING UNDER "D", "d" CONDITION.**

**CAUTION:**

DO NOT MOVE SPEED RANGE SELECTOR KNOB WHILST THE SPINDLE IS ROTATING.

**SPINDLE SPEED CALCULATIONS**

AS A TWO RANGE VARIABLE SPEED DRIVE IS AVAILABLE TO THE SPINDLE IT IS POSSIBLE TO MACHINE A PARTICULAR MATERIAL AT ITS OPTIMUM SURFACE SPEED, HENCE SET THE SPINDLE SPEED IN REV/MIN AND CALCULATE THE OPTIMUM POWER AVAILABLE.

THE OPTIMUM SPINDLE SPEED IS CALCULATED FROM THE FORMULAE SHOWN BELOW.

1)

$$N = \frac{S \times 1000}{\pi D} \quad (\text{METRIC})$$

WHERE D = DIAMETER IN MM

S = CUTTING SPEED IN Metres/min

AND N = SPINDLE rev / min

2)

$$N = \frac{S \times 1000}{X D} \quad (\text{INCH})$$

WHERE D = DIAMETER IN INCHES

S = CUTTING SPEED IN feet / min

AND N = SPINDLE rev/min

#### 5.4 TO START THE MACHINE

- (1) SWITCH ON THE MAIN ISOLATOR LOCATED AT THE REAR OF THE MACHINE.
- (2) RELEASE THE EMERGENCY STOP BUTTON (A) ON THE FRONT OF THE HEADSTOCK.
- (3) SWITCH ON THE KEY SWITCH (C).
- (4) SELECT ONE OF THE SPINDLE SPEED RANGE USING THE LEVER ON THE HEADSTOCK. (SEE PREVIOUS SECTION)




FIG. 8

#### 5.5 SPINDLE FORWARD-REVERSE SELECTION KNOB

PULL THE SELECTIVE KNOB (16 IN FIG. 6) UP, THE MOTOR WILL BE START AND THE SPINDLE WILL GET A FORWARD ROTATION WHILE OPERATING. ON THE CONTRACT, PUSH DOWN THE SELECTIVE KNOB THE MOTOR WILL BE START AND THE SPINDLE WILL GET A REVERSE ROTATION WHILE OPERATING.

#### 5.6 FORWARD-REVERSE SELECTION KNOB

TURN THE SELECTIVE KNOB (25 IN FIG. 6) TO RIGHT POSITION, THE LEAD SCREW WILL GET A COUNTERCLOCKWISE ROTATION OR THE FEED ROD WILL GET A CLOCKWISE ROTATION WHILE OPERATING. ON THE CONTRARY, TURN THE SELECTIVE KNOB TO LEFT POSITION, THE LEAD SCREW WILL GET A CLOCKWISE ROTATION OR FEED ROD WILL GET A COUNTERCLOCKWISE ROTATION WHILE OPERATING.

FEEDS / THREADS CHANGE KNOB (21 IN FIG. 6) IS FITTED WITH THE COVER OF GEAR BOX. TURN THE CHANGE KNOB TO RIGHT POSITION, FEED ROD WILL TURN FOR FEEDING AUTOMATICALLY. TURN THE CHANGE KNOB TO LEFT POSITION, THE LEAD SCREW WILL TURN, THREADS IS READY.

#### 5.7 THREADING

BY PROPER LOCATION OF THE SHIFTING LEVERS, 40 INCH THREADS AND CORRESPONDING FEEDS ARE POSSIBLE. THE THREAD CUTTING CHARTS GIVE FULL DETAILS OF THE INCH AND METRIC THREADS AVAILABLE.

#### 5.8 HALF NUT CONTROL LEVER






PUSH THE HALF NUT LEVER (17 IN FIG. 6) DOWN WHEN THE LEAD SCREW IS REVOLVING TO ENGAGE THE HALF NUT FOR THREADING. PULLING THIS LEVER UP WILL DISENGAGE THE HALF NUT.

#### 5.9 LONGITUDINAL AND CROSS FEED ENGAGEMENT LEVER



THIS IS A THREE POSITION CONTROL WITH THE MIDDLE POSITION AS NEUTRAL. PUSH THE LEVER 18 IN FIG. 6) DOWN TO ENGAGE THE CROSS FEEDS AND LIFT UP TO ENGAGE THE LONGITUDINAL FEEDS.


## FEED AND THREAD TABLE FOR INCH SPECIFICATION

### FOR CUTTING METRIC THREAD

METRIC THREAD PITCH 			1	2	4	5	6
	40	A	6				4
	127	B	3				2
	120	C	1.5				1
	40	D	0.75		0.6		0.5
		E			0.3		0.25
	40	A	7.5		6		5
	127	B			3		2.5
	120	C			1.5		1.25
	32	D			0.75		
		E					
	30	A	4.5	4			3
	127	B		2			1.5
	120	C		1	0.9		0.75
	40	D		0.5	0.45		
		E		0.25	0.225		
	32	A					
	127	B					
	120	C					0.8
	40	D	0.6				0.4
		E	0.3				0.2







### FOR CUTTING INCH THREAD

THREAD PER INCH 			1	2	3	4	5	6	7	8
	40	A	4	4 1/2	4 3/4	5	5 1/2	6	6 1/2	7
	127	B	8	9	9 1/2	10	11	12	13	14
	120	C	16	18	19	20	22	24	26	28
	40	D	32	36	38	40	44	48	52	56
		E	64	72	76	80	88	96	104	112



RANGE OF FEED			IN	IN
	30	A	.0081 ~ .0046	.0468 ~ .0267
	127	B	.0040 ~ .0023	.0234 ~ .0134
	120	C	.0020 ~ .0012	.0117 ~ .0067
	40	D	.0010 ~ .0006	.0058 ~ .0033
		E	.0005 ~ .0003	.0029 ~ .0017


## FEEDS AND THREAD TABLE FOR METRIC SPECIFICATION

### FOR CUTTING METRIC THREAD

METRIC THREAD PITCH 			1	2	4	6	8
	40	A	6				4
	127	B	3				2
	120	C	1.5				1
	40	D	0.75		0.6		0.5
		E			0.3		0.25
	40	A	7.5		6		5
	127	B			3		2.5
	120	C			1.5		1.25
	32	D			0.75		
		E					
	30	A	4.5	4			3
	127	B		2			1.5
	120	C		1	0.9		0.75
	40	D		0.5	0.45		
		E		0.25	0.225		
	32	A					
	127	B					
	120	C					0.8
	40	D	0.6				0.4
		E	0.3				0.2
	42	A	7				4
	127	B	3.5				2
	120	C	1.75				1
	36	D			0.7		0.5
		E			0.35		0.25

### FOR CUTTING INCH THREAD

THREAD PER INCH 			1	2	3	4	5	6	7	8
	40	A	4	4 1/2	4 3/4	5	5 1/2	6	6 1/2	7
	120	B	8	9	9 1/2	10	11	12	13	14
	127	C	16	18	19	20	22	24	26	28
	40	D	32	36	38	40	44	48	52	56
		E	64	72	76	80	88	96	104	112

RANGE OF FEED			mm	mm
	40	A	0.269 ~ 0.154	1.583 ~ 0.905
	127	B	0.135 ~ 0.077	0.792 ~ 0.452
	120	C	0.067 ~ 0.038	0.396 ~ 0.226
	40	D	0.034 ~ 0.019	0.198 ~ 0.113
		E	0.017 ~ 0.010	0.099 ~ 0.057



## 5.10 THREAD INDICATOR

THE THREAD INDICATOR IS MOUNTED ON THE RIGHT HAND SIDE OF THE CARRIAGE AND IS ENGAGED WITH THE LEADSCREW. THE INDICATOR DIAL HAS 8 LINES, 4 OF WHICH ARE NUMBERED 1, 2, 3 AND 4. WHEN THE CARRIAGE IS STATIONARY AND THE LEAD SCREW IS REVOLVING, THE THREADING DIAL IS TURNING. A REFERENCE LINE IS IN THE HOUSING AND IS USED FOR REFERENCE ENGAGEMENT OF THE HALF NUT THERE IS AN INDICATOR TABLE IN THE THREADING CHART WHICH GIVES THE SELECTION OR SEQUENCE OF REVOLVING LINES WHICH CAN BE USED FOR A GIVEN INCH THREAD PITCH.

WHEN 1-4 IS INDICATED IT MEANS THAT THE HALF NUT CAN BE ENGAGED ON THE LINES ENGRAVED 1, 2, 3, OR 4.

WHEN 1-3 IS INDICATED, THE HALF NUT IS ENGAGED ON LINES ENGRAVED 1 AND 3.

THE SAME APPLIES WHEN THE INDICATOR CALL FOR 2-4.

THE INDICATOR CHART WILL ALSO REFER TO 1-8 WHICH MEANS THAT THE HALF NUT CAN BE ENGAGED ON ANY OF THE 8 LINES ON THE THREADING DIAL INDICATOR FOR SUCCESSIVE CUTS.

### IMPORTANT

1. IF THE LATHE IS EQUIPPED WITH AN INCH LEAD SCREW, THE DIAL INDICATOR CAN ONLY BE USED FOR CUTTING INCH THREADS.

WHEN CUTTING METRIC THREADS THE HALF NUT IS NEVER DISENGAGED. AT COMPLETION OF A THREADING CUT, THE CUTTING TOOL IS RETRACTED AND THE SPINDLE STOPPED. THE SPINDLE ROTATION IS REVERSED WHICH BRINGS THE CARRIAGE BACK TO THE BEGINNING POSITION. BY GOING BACK AND FORTH SUCCESSIVE CUTS ARE TAKEN TO THE REQUIRED THREAD DEPTH.

2. MAKE SURE THAT THE APPROPRIATE INDICATOR LINE ALWAYS COINCIDES WITH THE FIXED LINE ON EACH CUT.

FOR INCH SPECIFICATION      FOR METRIC SPECIFICATION

THREAD INDICATOR PLATE					
T.P.I.	SCALE	T.P.I.	SCALE	T.P.I.	SCALE
4	1-8	12	1-8	38	1-8
4½	$\frac{1}{2} \frac{3}{4}$	13	1-4	40	1-8
4¾	1	14	1-8	44	1-8
5	1-4	16	1-8	48	1-8
5½	$\frac{1}{2} \frac{3}{4}$	18	1-8	52	1-8
6	1-8	19	1-4	56	1-8
6½	$\frac{1}{2} \frac{3}{4}$	20	1-8	64	1-8
7	1-4	22	1-8	72	1-8
8	1-8	24	1-8	76	1-8
9	1-4	26	1-8	80	1-8
9½	$\frac{1}{2} \frac{3}{4}$	28	1-8	96	1-8
10	1-8	32	1-8	104	1-8
11	1-4	36	1-8	112	1-8

INDICATOR TABLE			
GEAR	SCALE	PITCH	
28T		0.35	0.7 1.75
		3.5	7
24T		2	6
	ANYWHERE	0.2	0.25 0.3
		0.5	0.6 0.75
		1	1.5 3
		2.25	0.45 0.9
		4.5	
20T		0.4	2 6
		0.8	4
		1.25	2.5 5
		7.5	
		0.4	2 6




FIG. 10

THREAD INDICATOR PLATE (FIG. 9)

### 5.11 AUTOMATIC FEEDING

- (1). PUT THE POSITIVE-REVERSE SELECTIVE KNOB TO THE POSITION WHICH IS NEEDED.
- (2). TURN THE TWO GEAR BOX SPEEDS CHANGE KNOB AND GEAR BOX SPEEDS SELECTIVE DISH.
- (3). TURN THE FEEDS AND THREADS SELECTIVE KNOB TO THE LEFT, THE FEED ROD (5 IN FIG. 8) WILL TURN.
- (4). PUSH DOWN THE AUTO-FEEDING SELECTOR (5 IN FIG. 11), THE MACHINE WILL HAVE A CROSS AUTOMATICALLY FEEDING. PULL THE LEVER (5 IN FIG. 11) UP, THE MACHINE WILL HAVE A LONGITUDINAL AUTOMATICALLY FEEDING.

IF YOU WANT TO FEED BY HAND, JUST PUT ALL THE LEVER BACK TO THE ORIGINAL POSITION, THE MACHINE IS NOW UNDER HAND WHEEL CONTROL. TURN THE HAND WHEEL (4 IN FIG. 11) AND MACHINE CAN MAKE THE LONGITUDINAL FEEDING.

### 5.12 TOOL POST AND SADDLE

- (1). MOVE SADDLE BY HANDLE WHEEL (9 IN FIG. 11).
- (2). CROSS MOVEMENT OF THE TOOL POST IS ACCOMPLISHED BY TURNING THE HANDLE (3 IN FIG. 11). THE TOOL POST WILL MOVE TOWARDS THE CENTER WHEN TURNING THE HANDLE CLOCKWISE.
- (3). BOTH THE CROSS-SLIDE AND COMPOUND SLIDE CAN BE LOCKED.

### 5.13 TAILSTOCK

THE ALIGNMENT OF THE TAILSTOCK WITH THE HEAD STOCK IS INSURED BY A "VEE" AND A "FLAT" IN THE MACHINE BED. ONCE POSITIONED IT IS LOCKED TO THE BED BY THE LEVER (2 IN FIG. 12) LOCATED AT THE BACK OF THE TAILSTOCK.

THE TAILSTOCK BODY (5 IN FIG. 12) MOUNTED ON A FIRM BASE (6 IN FIG. 12) AND MAY BE ADJUSTED BY MEANS OF AN ADJUSTING SCREW (7 IN FIG. 12) ON THE SIDE OF THE BODY FOR OFF-SETTING THE CENTER, CARRIED IN THE TAIL STOCK QUILL TO PERMIT TAPERS TO BE TURNED FOR LINING UP THIS CENTER WITH THAT IS IN THE HEAD STOCK SPINDLE. THE TAIL STOCK QUILL IS LOCKED BY MEANS OF A QUILL CLAMPING LEVER (1 IN FIG. 12).




FIG. 11




FIG. 12

### 5.14 COOLANT


THE COOLANT PUMP IS FITTED TO THE COOLANT TANK AND IS OPERATED BY THE ON/OFF SWITCH LOCATED ON THE ELECTRIC BOX CONTROL PANEL.

THE COOLANT TANK IS LOCATED AT THE BACK OF THE MACHINE AND HAS A CAPACITY OF 11.2 LITRES.

REGARDING CUTTING FLUID, WE SUGGEST THAT USING 76 U.S.A CALIFORNIA SOLUBLE OIL 10.

## 6 DAILY SERVICE

### 6.1 POSITION OF LUBRICATION AND FILLING DEVICES



LUBRICATION CHART (FIG. 13)

1. HEAD STOCK OILING INLET
2. GEAR BOX OILING INLET
3. CHANGE GEAR OILING INLET
4. SADDLE OILING INLET
5. TAILSTOCK OILING INLET
6. FEED ROD BRACKET OILING INLET
7. APRON OILING INLET

### 6.2 DAILY MAINTENANCE FOR OPERATORS

#### LUBRICATION

- (1). ALWAYS KEEP IN MIND THAT THE ACCURACY AND LONG LIFE OF THE LATHE DEPENDS ON PROPER CARE AND LUBRICATION.
- (1) BEFORE START-UP, MAKE SURE THAT THE FOLLOWING ARE PROPERLY LUBRICATED: HEAD STOCK, GEAR BOX, CROSS SLIDE, TOOL SLIDE, TOOL POST, SADDLE, APRON, TAIL STOCK, LEAD SCREW, FEED SHAFT AND SCREW BRACKET AND THE BEDWAYS.

**NOTE:** USE ONLY TOP QUALITY INDUSTRIAL LUBRICANTS.

ISO SPEC.	CONSISTENCY cst@40°C	MOBIL	ESSO	TOTAL	SHELL
VG-68	68	DTE HEAVY MEDIUM	TERESSO 68	AZLLA ZS 68	TURBO T68

#### a. HEAD STOCK LUBRICATION

FILL AND MAINTAIN OIL LEVEL AS INDICATED IN SIGHT GLASS. DRAIN AND CHANGE OIL TWICE YEARLY.

#### b. QUICK CHANGE BOX LUBRICATION – FOUR TIMES DAILY

INSIDE GEARS OF GEAR BOX ARE LUBRICATED BY OIL GOT INTO THROUGH THE LUBRICATING POINT COVERED BY OIL CAP TO THE CAVITY ON TOP OF THE GEARBOX WHERE HAS A SPONGE TO RETAIN LUBRICATING OIL FOR CONSTANT DRIPPING INTI THE 14 HOLES.

#### c. CHANGE GEAR LUBRICATION - TWICE A MONTH

OPEN SIDE COVER OF HEAD STOCK AND FEED OIL ON THE GEARS DIRECTLY.

#### d. SLIDEWAYS

THE GUIDES OF SADDLE, CROSS SLIDE, COMPOUND SLIDE, TAIL STOCK AND BEDWAYS SHOULD RECEIVE A LIGHT FILM OF OIL.

MAKE SURE THAT THE COMPOUND SCREW AND NUT, CROSS FEED SCREW AND NUT AS WELL AS THE LEAD SCREW AND HALF NUT ARE PROPERLY LUBRICATED.

#### e. TAIL STOCK – ONCE DAILY

OIL THROUGH OILIER FITTED ON TOP OF TAILSTOCK.

#### f. LEAD SCREW AND FEED ROD LUBRICATION – AT LEAST ONCE OR TWICE DAILY

## 7 ADJUSTMENT

EACH ASSEMBLY WAS ADJUSTED AND SUBJECTED TO QUALITY AND ACCURACY TESTS PRIOR TO LEAVING THE FACTORY, HOWEVER RE-ADJUSTMENT MAY BE REQUIRED AFTER SOMETIMES AND THE FOLLOWING PROCEDURES SHOULD BE FOLLOWED.

### 7.1 LEVEL

THE LEVEL OF THE MACHINE IS A MAJOR FACTOR WHICH WILL INFLUENCE THE ACCURACY OF THE LATHE. SINCE THE FOUNDATION AND OTHER COMPONENTS WILL ALTER THE MACHINE LEVEL, REGULAR CHECK IS ESSENTIAL.

### 7.2 MAIN SPINDLE BEARING ADJUSTMENT

THE FRONT ROLLER BEARING IS A #30212 AND THE REAR ROLLER BEARING IS A #30210.

THESE BEARINGS HAVE BEEN PROPERLY ADJUSTED BEFORE LEAVING THE FACTORY. IF THEY BECOME LOOSE AFTER SOMETIMES, ADJUSTMENT CAN BE MADE BY FIRST REMOVING THE REAR BEARING CAP #CF-1105-01 AND RETIGHTENING THE SPINDLE LOCK-NUT #CF-1110-01 SO TO HAVE THE MINIMUM RADIAL AND AXIAL PLAY. DO NOT ADJUST THE BEARINGS TOO TIGHT AS IT WILL CAUSE SPINDLE OVERHEATING AT HIGH SPEED.




FIG. 14

### 7.3 ADJUSTMENT OF SADDLE AND CROSS-SLIDE FEED OVERLOAD

HERE IS A FEED OVERLOAD CLUTCH IN THE APRON WHICH IS ADJUSTED BY TURNING THE ADJUSTMENT SCREW (8 IN FIG. 11) CLOCKWISE IF THE SADDLE OR CROSS-SLIDE STOPS WHILE TAKING A CUT. CARE MUST BE TAKEN NOT TO OVERTIGHTEN THIS SAFETY DEVICE AS YOU WILL NOT HAVE AN OVERLOAD PROTECTION.

### 7.4 ADJUSTMENT OF TAPER GIB

THERE IS A TAPER GIB ON THE CROSS SLIDE AND TOOL SLIDE RESPECTIVELY. ADJUST A TAPER GIB IN A SUCCESSIVE ORDER AS FOLLOWS:

ADJUSTMENT OF A CROSS SLIDE GIB: (FIG. 15)

- LOOSEN AN ADJUSTING SCREW (2) AT THE REAR AND TIGHTEN AN ADJUSTING SCREW (3) IN THE FRONT.
- TURN CROSS SLIDE HANDLE AND MAKE SURE WHETHER A TAPER GIB HAS BEEN ADJUSTED. IF IT IS WELL ADJUSTED THEN TIGHTEN AN ADJUSTING SCREW (3)

ADJUSTMENT OF A TOOL SLIDE GIB:

TIGHTEN AN ADJUSTING SCREW (1), AND THEN TURN THE HANDLE OF TOOL SLIDE TO MAKE SURE WHETHER A TAPER GIB HAS BEEN ADJUSTED.  
ADJUSTMENT OF SADDLE GIB (FIG. 16)

SADDLE IS MOUNTED ON BEDWAY. IN ORDER TO KEEP LEVELING ACCURACY, THERE IS A PLANE GIB TO BE ADJUSTED AS SHOWN IN FIGURE. IF THERE EXISTS EXCESS CLEARANCE

BETWEEN SADDLE AND BEDWAY, LOOSEN THE FIXING NUT THEN FASTEN THE ADJUSTING BOLT IN RIGHT-HAND ROTATION. THE PLANE GIB WILL BE PUSHED TO PROPER POSITION AND THEN FASTEN THE FIXING NUT AGAIN.




FIG. 15




FIG. 16

### 7.5 CROSS SLIDE NUT

THE CROSS SLIDE NUT CAN BE ADJUSTED TO MINIMIZE THE BACK-LASH ON THE CROSS SLIDE SCREW. THIS ADJUSTMENT IS CARRIED OUT BY TIGHTENING THE CAP SCREW WHICH IS FITTED TO THE NUT AND WHICH CAN BE REACHED FROM THE REAR OF THE LATHE AFTER MOVING THE CROSS SLIDE TOWARDS THE BACK OF THE MACHINE.

### 7.6 ALIGNMENT OF THE TAILSTOCK

THE TAILSTOCK ASSEMBLY IS COMPRISED OF A BASE AND THE QUILL CASTING AND CAN BE ADJUSTED TO PERFECTLY LINE UP WITH THE HEADSTOCK SPINDLE AXIS OR CAN BE OFF-SET IN ORDER TO PRODUCE SHALLOW TAPERS.

### 7.7 TAILSTOCK LOCKING BOLT ADJUSTMENT

IF THE TAILSTOCK DOES NOT CLAMP POSITIVELY THE BED WHEN ACTUATING LEVER (2 IN FIG. 12) READJUST THE CLAMPING BOLT NUT (FIG. 17)

### 7.8 BACKLASH ADJUSTMENT OF SADDLE LEADSCREW (FIG. 18)

THERE IS A FRICTION BETWEEN LEADSCREW AND SCREW NUT OF SADDLE AFTER LONG USE OF THE PARTS SO IT WILL BE WEAR PRODUCED. IN ORDER TO ELIMINATE THE EXCESS CLEARANCE, THE ADJUSTING BOLT SHOULD BE ADJUSTED. ITS ADJUSTING METHOD: AT FIRST, ROTATE THE LEADSCREW TO BACK END, FASTEN THE ADJUSTING BOLT TO PROPER POSITION THAT THE CLEARANCE BETWEEN LEADSCREW AND LEADSCREW NUT IS ADEQUATE.




FIG. 17




FIG. 18

## CONTENT

---

### 1. HEAD STOCK

#### 1.1 GEARSHIFT

#### 1.2 GEARING

### 2. TAIL STOCK

### 3. CARRIAGE

### 4. TOOL SLIDE

### 5. BED, LEAD SCREW AND FEED ROD ASSEMBLY

### 6. APRON

### 7. GEAR BOX

### 8. MOTOR, THREAD INDICATOR AND CHANGE GEAR ASSEMBLY

### 9. BRAKE ACCESSORIES

### 10. PROTECTION GUARD ASSEMBLY

### 11. ELECTRICAL COMPONENTS AND LAYOUT

### 12. CONTROL PANEL, SWITCHES AND SYMBOLS


### 13. POWER CIRCUIT

### 14. SCHEDULE OF ELECTRICAL EQUIPMENT


# 1. HEAD STOCK

## 1.1 GEARSHIFT

01. SEAL CAP	CF-6026-00	16. KEY	5X5X12
02. SHAFT	CF-1037-01	17. GEAR SHAFT	CF-1041-01
03. HALF GEAR	CF-1039-R2	18. SHAFT FORK	CF-1034-00
04. HEX. SOCKET HEAD SCREW	M6X30	19. SPRING PIN	5X24
05. OPERATING LEVER	CF-1035-01	20. GEAR	CF-1044-00
06. RETAINING RING	E-12	21. HALF GEAR	CF-1039-L2
07. SEAL CAP	CF-6028-00	22. OPERATING LEVER	CF-1035-01
08. HANDLE KNOB	CF-1042-01	23. HANDLE KNOB	CF-1126-01
09. CYLINDRICAL HANDLE		24. O RING	P-12
10. CONTROL LEVER	CF-6047-00	25. OPERATING LEVER	CF-1128-01
11. SET SCREW	M8X12	26. SHAFT	CF-1130-00
12. SPRING		27. SLIDING BLOCK	EK-1129-00
13. HUB	CF-1046-00	28. SET SCREW	M8X10
14. STEEL BALL	5/16"	29. SPRING	
15. O RING	P-22	30. STEEL BALL	1/4"



## 1.2 GEARING






## 1.2 GEARING

01. HEX. SOCKET HEAD SCREW	M6X16	35. O RING	P-16
02. WASHER	CF-6068-00	36. C SHAFT	CF-1111-00
03. V-BELT PULLEY	CF-1017-03	37. GEAR	CF-1114-S0
04. OIL SEAL	TC 20 35 8	38. WASHER	CF-1112-A0
05. HEX. SOCKET HEAD SCREW	M6X16	39. RETAINING RING	S-26
06. BALL BEARING	6204L	40. KEY	5X5X22
07. A SHAFT BEARING CAP	CF-1019-01	41. KEY	8X8X62
08. PACKING	CF-1119-01	42. SPINDLE	CF-1076-A1
09. KEY	6X6X35	43. CAMLOCK STUD	CF-7073-00
10. A SHAFT	CF-1014-S3	44. CAM	CF-1071-00
11. KEY	6X6X15	45. STOP BOLT FOR CAMS	CF-1072-00
12. GEAR	CF-1032-S3	46. SPRING	
13. BALL BEARING	6203LL	47. HEX. SOCKET HEAD SCREW	M6X16
14. B SHAFT BEARING CAP	CF-1063-00	48. PACKING	CF-1177-00
15. BALL BEARING	6203L	49. FRONT BEARING CAP	CF-1077-01
16. GEAR	CF-1057-S1	50. HEX. SOCKET HEAD SCREW	M6X16
17. RETAINING RING	S-22	51. RETAINING RING	S-19
18. B SHAFT	CF-1051-G0	52. BALL BEARING	6004L
19. GEAR	CF-1060-S0	53. OIL SEAL	TC 20 35 8
20. BALL BEARING	6303L	54. BEARING CAP	CF-1122-01
21. B SHAFT BEARING CAP	CF-1062-01	55. PACKING	CF-1123-01
22. O RING	P-41	56. D SHAFT	CF-1118-00
23. HEX. SOCKET HEAD SCREW	M6X20	57. KEY	5X5X14
24. REAR BEARING CAP	CF-1105-01	58. KEY	5X5X22
25. PACKING	CF-1106-00	59. BALL BEARING	6004L
26. COPPER WASHER	EK-1109-00	60. RETAINING RING	S-20
26a. SET SCREW	M6X6	61. GEAR	CF-1125-S0
27. SPINDLE LOCK NUT	CF-1110-01	62. RETAINING RING	S-20
28. TAPER ROLLER BEARING	30210	63. PACKING	CF-1008-00
29. RETAINING RING	S-50	64. HEAD STOCK COVER	CF-1009-00
30. GEAR	CF-1089-S0	65. HEX. SOCKET HEAD SCREW	M6X25
31. RETAINING RING	S-55	66. HEX. SOCKET HEAD SCREW	M6X16
32. GEAR	CF-1084-S0	67. HEAD STOCK CASTING	CF-1801-B1
33. GEAR	CF-1083-S0	68. GP SCREW	1/2"-UNC
34. TAPER ROLLER BEARING	30212		

## 2. TAIL STOCK

01. FEED SCREW	CF-2008-00	17. TAILSTOCK BASE	CF-2831-00
02. PIN	MB-7009-00	18. CLAMPING PLATE	CF-2033-01
03. THRUST BALL BEARING	51101	19. SET SCREW	M6X6
04. SCREW HOLDER	CF-2011-00	20. SET SCREW	CF-2027-00
05. OIL BALL	1/4"	21. SHAFT CLAMPING	CF-2028-00
06. HEX. SOCKET HEAD SCREW	M6X20	22. SHAFT CLAMPING BOLT	CF-2021-00
07. HANDLE WHEEL DIAL (I)	CF-2005-I 0	23. LEVER STUD	CF-2018-00
HANDLE WHEEL DIAL (M)	CF-2005-M0	24. NUT	1/2"-12UNC
08. HANDLE WHEEL	CF-2004-00	25. WASHER	1/2"
09. WASHER	CF-7020-00	26. TAILSTOCK QUILL	CF-2015-00
10. NUT	MB-7014-00	27. GUIDE PIN	CF-2017-00
11. CLAMPING BOLT	CF-2030-01	28. TAILSTOCK CASTINGS	CF-2001-00
12. CYLINDRICAL KNOB		29. SET SCREW	M6X25
13. HANDLE KNOB	CF-2026-00	30. CLAMP NUT	CF-2023-00
14. HANDLE KNOB	CF-2020-00	31. SET SCREW	M8X50
15. GRIP CLAMPING BALL		32. GIB	
16. HANDLE KNOB	CF-6044-00	33. FEED SPRING	CF-3035-00




01. HANDLE KNOB	CF-6044-00	17. WIPER	CF-3008-00
02. HANDLE WHEEL	DF-3036-00	18. SCREW SET BUSHING	CF-3025-01
03. FEED SPRING	CF-3035-00	19. HEX. SOCKET SCREW	M6X20
04. CROSS FEED DIAL		20. TAPER GIB	DF-3017-00
SINGLE DIAL, INCH	DF-3032- I 0	21. HEX. SOCKET HEAD SCREW	M6X50
SINGLE DIAL, METRIC	DF-3032-M0	22. CROSS FEED SCREW BUSHING	
DUAL DIAL, IMPERIAL	DF-3033- I 0	FOR SINGLE DIAL	DF-3029-00
DUAL DIAL, METRIC	DF-3033-M0	FOR DUAL DIAL	DF-3030-00
05. DUAL DIAL INDICATING PLATE		23. GEAR	CF-3027-00
FOR IMPERIAL	DF-3034-I0	24. CROSS FEED SCREW & FEMALE	
FOR METRIC	DF-3034-M1	SCREW NUT	
06. ROUND HEAD SCREW	M4X6	FOR IMPERIAL	CF-3022- I 1
07. THRUST BALL BEARING	51101	FOR METRIC	CF-3022-M1
08. CROSS SLIDER	CF-3016-00	25. SADDLE	CF-3001-00
CROSS SLIDER T SLOT	CF-3016-T0	27. HEX. SOCKET SCREW	M6X16
09. GIB ADJUSTING SCREW	CF-3057-00	28. CLAMPING PLATE	CF-3112-01
10. NUT	M12	29. WIPER	CF-3009-00
11. HEX. SOCKET HEAD SCREW	M8X16	30. HEX. SOCKET HEAD SCREW	M8X20
12. CLAMPING PLATE	CF-3012-00	31. LOCK METAL PIECE	CF-3113-00
13. WIPER	CF-3007-00	32. CLAMPING PLATE	CF-3013-00
14. ROUND HEAD SCREW	M6X10	33. SET SCREW	M6X20
15. WASHER	CF-3020-00	34. NUT	M6
16. SADDLE LOCKING HANDLE	CF-3021-00	35. OIL BALL	




#### 4. TOOL SLIDE

01. COMPOUND SLIDE	CF-3055-00	(FOR METRIC)	DF-3044-M0
COMPOUND SLIDE T SLOT	CF-3055-T0	18. THRUST BALL BEARING	51101
1a. OIL BALL	1/4"	19. COMPOUND SCREW BUSHING	
02. LOCK PIN	CF-3060-00	FOR SINGLE DIAL	DF-3046-00
03. SPRING		FOR DUAL DIAL	DF-3047-00
04. SQUARE TURRET SHAFT	CF-3061-00	20. SPACER	CF-3065-00
SQUARE TURRET SHAFT T SLOT	CF-3061-T0	21. HEX. SOCKET HEAD SCREW	M6X20
05. TOOL POST WRENCH	CF-3068-00	22. LOCK NUT FOR SWIVEL	CF-3039-00
06. SQUARE HEADED BOLT	DF-3064-00	23. COMPOUND SLIDE DIAL	
07. 4 WAY TOOL POST	CF-3063-00	SINGLE DIAL IMPERIAL	DF-3048-I 0
08. TOOL POST LOCKING NUT	CF-3066-00	SINGLE DIAL METRIC	DF-3048-M0
09. HANDLE	CF-3067-00	DUAL DIAL IMPERIAL	DF-3049-I 0
10. CYLINDRICAL KNOB		DUAL DIAL METRIC	DF-3049-M0
11. GIB ADJUSTING SCREW	CF-3057-00	24. DUAL DIAL INDICATING PLATE	
12. TAPER GIB	CF-3056-00	FOR IMPERIAL	DF-3050-I 0
13. SWIVEL	CF-3838-00	FOR METRIC	DF-3050-M0
14. HEX. SOCKET HEAD SCREW	M8X16	25. ROUND HEAD SCREW	M4X6
16. LOCKING SCREW	CF-3058-00	26. HANDLE WHEEL	DF-3052-00
17. COMPOUND SLIDE LEAD SCREW		27. FEED SPRING	CF-3035-00
& COPPER NUT		28. NUT	M12
(FOR IMPERIAL)	DF-3044-I 0	29. HANDLE KNOB	DF-3053-00




## 5. BED, LEADSCREW AND FEED ROD ASSEMBLY

01. BED FOR 11CF	CF-6401-01	FORWARD - REVERSE CONTROL	
BED FOR 16CF	CF-6601-01	LEVER FOR 16CF	CF-6692-00
GAP BED FOR 11CF	CF-6402-01	18. WASHER	CF-6440-00
GAP BED FOR 16CF	CF-6602-01	19. WORM	CF-6439-R0
02. 11CF LEADSCREW FOR IMPERIAL	CF-6416-I0	20. HEX. SOCKET HEAD SCREW	M8X25
11CF LEAD SCREW FOR METRIC	CF-6416-M0	21. WORM CASTING	CF-6441-00
16CF LEADSCREW FOR IMPERIAL	CF-6616-I0	24. BUSHING	CF-6104-0 2
16CF LEAD SCREW FOR METRIC	CF-6616-M0	25. BRACKET	CF-6103-0 4
03. HEX. SOCKET HEAD SCREW	M6X16	26. OPERATING HANDLE	CF-6106-01
04. SPRING PIN	5X24	27. SPRING	
05. RACK FOR 11CF	CF-6407-00	28. BRACKET	CF-6105-02
RACK FOR 11CF GAP BED &	CF-6407-G0	29. SET SCREW	M8X8
WHEEL ON APRON LEFT	EK-6507-00	30. SPRING PIN	5X30
RACK FOR 16CF	CF-6607-00	31. STEEL BALL	1/4"
RACK FOR 16CF GAP BED &	CF-6407-G0	32. SPRING	
WHEEL ON APRON RIGHT	EK-6707-00	33. SET SCREW	M8X6
06. OIL GAP	1/4	34. HEX. SOCKET HEAD SCREW	M6X45
07. BRACKET	CF-6010-30	35. LIMIT SWITCH COVER	CF-6109-01
08. HEX. SOCKET HEAD SCREW	M8X35	35a. ROUND SCREW	M3X25
09. SPRING PIN	5X60	35b. LIMIT SWITCH	
10. HEX. SOCKET HEAD SCREW	M8X50	36. SPACER	CF-6107-00
11. SET SCREW	M6X20	37. HEX. SOCKET HEAD SCREW	M6X16
12. NUT	M6	38. HEX. SOCKET HEAD SCREW	M6X12
13. HEX. SOCKET HEAD SCREW	M6X16	39. LOCKING BRACKET	CF-6101-01
14. GRIP		39a. HEX. SOCKET HEAD SCREW	M6X12
15. KEY	CF-6239-00	39b. LIMIT SWITCH	
16. FEED ROD FOR 11CF	CF-6425-00	40. NUT	M10
FEED ROD FOR 16CF	CF-6625-00	41. SIDE COVER	CF-6880-C1
17. FORWARD - REVERSE CONTROL		42. SIDE COVER LOCKING SCREW	CF-6881-00
LEVER FOR 11CF	CF-6492-00	43. SIDE COVER HOLE GUARD	CF-6090-00
		44. ROUND SCREW	M5X10




## 6. APRON



01. GEAR	CA-4010-00	30. SPRING	
1a. O RING	P-12	31. SET SCREW	M8X6
02. KEY	5X5X14	32. SPRING PIN	5X24
03. O RING	P-22	33. NUT	5/8"-UNF
04. BUSHING	CA-4007-A0	34. WORM GEAR	CA-4037-R0
06. SET SCREW	M6X6	35. O RING	P-22
07. HAND WHEEL	CA-4003-A1	36. GEAR 21 T	CA-4036-01
7a. DIAL (IMPERIAL)	CA-4004- I 0	37. SPRING	CA-4035-00
DIAL (METRIC)	CA-4004-M0	38. SPRING PIN	5X24
7b. FEED SPRING	CF-3035-00	39. BUSHING	CA-4033-00
08. HANDLE	CF-6044-00	40. O RING	P-12
09. GEAR SHAFT 13 T	CA-4013-00	41. O RING	P-22
10. KEY	5X5X14	42. SHAFT	CA-4031-00
11. GEAR 50 T	CA-4011-01	43. SET SCREW	M8X20
12. RETAINING RING	E-12	44. HALF NUT BRACKET	
13. RETAINING RING	S-16	(IMPERIAL)	CA-4442- I 0
14. GEAR 30 T	CA-4023-01	(METRIC)	CA-4442-M0
15. WASHER	CF-6068-00	45. HALF NUT CLUTCH AXLE	CA-4049-A1
16. SHAFT	CA-4022-01	45a. SHAFT	CA-4049-B1
17. HEX. SOCKET HEAD SCREW	M6X20	46. SAFETY BRACKET	CA-4050-02
18. SET SCREW	M6X6	47. SPRING PIN	5X40
19. APRON CASTING		48. OIL GLASS	
(LEFT HAND WHEEL)	CA-4001-L1	49. SET SCREW	M8X6
(RIGHT HAND WHEEL)	CA-4001-R1	50. GIB FOR HALF NUT	CA-4046-00
20. GEAR 24 T	CA-4015-00	51. SET SCREW	M8X6
21. RETAINING RING	E-12	52. SPRING	
22. AXLE	CA-4019-00	53. STEEL BALL	1/4"
23. GEAR 39 T	CA-4017-01	54. SPRING PIN	5X30
24. GEAR 24 T	CA-4020-01	55. GRIP	
25. GEAR SHAFT	CA-4016-00	56. HANDLE	CF-6047-00
26. OIL CAP	1/4"	57. HANDLE BOSS	CA-4045-00
27. BRACKET	CA-4021-01	58. GEAR SHAFT	CA-4028-00
28. HEX. SOCKET HEAD SCREW	M6X35	59. CLUTCH HANDLE	CA-4029-00
29. STEEL BALL	1/4	60. GRIP	

## 7. GEAR BOX






## 7. GEAR BOX


01. HEX. SOCKET HEAD SCREW	M6X25	36. COPPER BUSHING	CA-5076-00
02. BEARING CAP	CA-5009-00	37. SHAFT	CA-5077-00
03. SHAFT	CA-5005-01	38. KEY	5X5X14
04. KEY	5X5X14	38a. SPRING PIN	5X24
05. BALL BEARING	6203Z	39. SHAFT	CA-5020-00
06. RETAINING RING	S-17	40. KEY	5X5X112
07. GEAR	CA-5012-00	41. BALL BEARING	6220Z
08. GEAR	CA-5017-00	42. RETAINING RING	S-15
09. NUT	EK-5075-00	43. BEARING CAP	CA-5021-00
10. SET SCREW	M6X6	44. ROUND SCREW	M6X10
11. GEAR 20T	CA-5073-00	45. BEARING CAP	EK-5038-00
12. THRUST BALL BEARING	51103	46. BEARING CAP	CA-5021-00
13. COPPER BUSHING	CA-5068-00	47. BALL BEARING	6202Z
14. THRUST BALL BEARING	51103	47a. RETAINING RING	S-15
15. KEY	5X5X14	48. SHAFT	CA-5036-00
16. SHAFT	CA-5069-01	49. SHIFTER	CA-5043-01
16a. TAPER PIN	CF-6015-00	49a. SET SCREW	M6X6
17. BEARING CAP	CA-5021-00	50. GEAR 32T	CA-5040-00
18. RETAINING RING	S-15	51. SHAFT	CA-5042-00
19. WASHER	EK-5023-A0	52. KEY	CA-5239-00
20. BALL BEARING	6202Z	53. GEAR 18T	CA-5039-00
21. GEAR 16T	CA-5019-00	54. BALL BEARING	6202Z
22. GEAR	CA-5017-00	55. BEARING CAP	EK-5022-00
23. GEAR	CA-5017-00	56. HANDLE KNOB	CA-5044-00
24. GEAR 16T	CA-5025-00	57. OIL CAP	
25. GEAR 18T	CA-5026-00	58. SHAFT FORK	CA-5066-00
26. GEAR 19T	CA-5027-00	59. OPERATING	CA-5064-01
27. GEAR 20T	CA-5028-00	60. HANDLE KNOB	CA-5057-01
28. GEAR 22T	CA-5029-00	61. STEEL BALL	1/4"
29. GEAR 24T	CA-5030-00	62. SPRING	
30. GEAR 26T	CA-5031-00	63. SET SCREW	M8X10
31. GEAR 28T	CA-5032-00	64. GEAR BOX CASTING	CA-5001-02
32. GEAR 28T	CA-5033-00	65. GEAR BOX COVER	CA-5453-01
33. NUT	EK-5075-00	66. HEX. SOCKET HEAD SCREW	M6X35
34. SET SCREW	M6X6	67. SPRING PIN	5X24
35. GEAR 20T	M6X6	68. HEX. SOCKET HEAD SCREW	M8X25

## 8. MOTOR, THREAD INDICATOR AND CHANGE GEAR ASSEMBLY

01. HEX. SOCKET HEAD SCREW	M8X20	CHANGE GEAR 36T	CF-6072-00
02. MOTOR BASE LOCKING BOLT	CF-6046-01	CHANGE GEAR 42T	CF-6073-00
03. NUT	M12	19. NUT	M10
04. FLAT SPACER	1/2"	20. RETAINING RING	S-15
05. V BELT FOR 50Hz	B33	21. BALL BEARING	6003Z
V BELT FOR 60Hz	B32	22. IDLE GEAR	CF-6065-00
06. MOTOR PULLEY FOR 50 Hz	CF-6055-00	23. CIRCLET	R-35
MOTOR PULLEY FOR 60 Hz	CF-6056-00	24. IDLE GEAR SHAFT	CF-6063-00
07. KEY	6X6X30	25. IDLE GEAR HOLDER	CF-6058-00
08. FLAT SPACER	1/2"	26. BOLT	CF-6062-00
09. NUT	M12	27. HEX. SOCKET HEAD SCREW	M8X45
10. SPRING PIN	4X20	28. THREAD INDICATOR BRACKET	CA-4062-00
11. MOTOR BASE SHAFT	CA-6049-00	29. THREAD INDICATOR	CA-4064-00
12. OPENED PIN	1/8"X1"	30. HEX. SOCKET HEAD SCREW	M6X50
13. SHAFT SCREW HOLDER	CF-6051-00	31. GEAR 32T (IMPERIAL)	CA-4065-I1
14. NUT	5/8-UNF	32. WASHER	
15. MOTOR BASE	CF-6042-00	33. HEX. SOCKET HEAD SCREW	M6X8
15a. HEX. HEAD SCREW	M8X25	34. HEX. SOCKET HEAD SCREW	M6X25
15b. SPRING WASHER	8mm	35. GEAR 28T (METRIC)	CA-4065-M1
16. HEX. SOCKET HEAD SCREW	M6X16	36. GEAR 20T (METRIC)	CA-4065-M2
17. SPACER	CF-6068-00	37. GEAR 24T (METRIC)	CA-4065-M3
18. CHANGE GEAR 40T	CF-6070-00	38. WASHER	1/4"
CHANGE GEAR 30T	CF-6069-00	39. MOTOR GUARD	CF-6083-E0
CHANGE GEAR 32T	CF-6071-00	40. ROUND SCREW	M5X6




## 9. BRAKE ASSEMBLY



## 9. BRAKE ASSEMBLY

01. V BELT PULLEY	CF-1017-03	21. NUT	M8
02. BRAKE SHOE LOCKING SCREW	CF-7040-00	22. BRAKE LINE COVER LOCKING SCREW	CF-7044-00
03. SPRING		23. NUT	M8
04. BRAKE SHOE		24. HEX. SOCKET HEAD SCREW	M8X20
05. HEX. SOCKET HEAD SCREW	M6X16	25. WASHER	
06. NUT	M10	26. SPRING	
07. BEARING CAP	CF-1019-01	27. NUT	M8
08. AXLE		28. HEX. SOCKET HEAD SCREW	M6X12
09. PIN		29. LIMIT SWITCH BASE	CF-7047-00
10. RETAINING RING	S-17	30. NUT	M6
11. BRAKE SHIFTER	CF-7042-00	31. LIMIT SWITCH	
12. BRAKE CAM	CF-7041-00	32. HEX. SOCKET HEAD SCREW	M6X20
13. O RING	P-12	33. NUT	M3
14. NUT		34. ROUND SCREW	M3X25
15. BRAKE LINE		35. HEX. SOCKET HEAD SCREW	M6X20
16. SPRING WASHER		36. BRACKET	CF-7046-00
17. BRAKE CABLE		37. NUT	M8
18. BRAKE CABLE LOCKING BOLT		38. BRACKET SHIFTER	CF-7045-00
19. FLOOR STAND		39. SPRING PIN	5X30
20. BRAKE CABLE COVER		40. BRAKE PEDAL	


# 10. PROTECTION GUARD ASSEMBLY




## **/0. PROTECTION GUARD ASSEMBLY**

01. HEX. SOCKET HEAD SCREW	M6X20
02. BUSHING	
03. PROTECTION COVER (L)	
04. HEX. SOCKET HEAD SCREW	M6X16
05. BUSHING	
06. LEAD SCREW ( INCH FOR 11CF )	CFF-6416-I0
LEAD SCREW (METRIC FOR 11CF)	CF-6416-M0
LEAD SCREW (INCH FOR 16DF)	CF-6616-I0
LEAD SCREW (METRIC FOR 16F)	CF-6616-M0
07. BRACKET	DF-7417-00
08. HEX. SOCKET HEAD SCREW	M6X20
09. PROTECTION COVER (R)	
10. HEX. SOCKET SCREW	M6X20
11. BUSHING	
12. SIDE COVER	CF-6880-C0
13. SET SCREW	M6X8
14. SPRING PIN	5X24
15. LIMIT SWITCH COVER	
16. LIMIT SWITCH	
17. LIMIT SWITCH BASE	
18. ROUND HEAD SCREW	M3X25
19. HEX. SOCKET HEAD SCREW	M6X16
20. SET SCREW	M6X8
21. SPLASH GUARD (FOR 11CF)	CF-7438-00
SPLASH GUARD (FOR 16CF)	CF-7638-00
22. LEVER	CF-7125-01
23. BRACKET	CF-7124-E0
24. HEX. SOCKET HEAD SCREW	M6X16
25. HEX. SOCKET HEAD SCREW	M6X16
26. SPACER	CF-6107-00
27. CHUCK GUARD	CF-7120-E0
28. CARRIAGE COVER	
29. HEX. SOCKET HEAD SCREW	M6X12
30. WASHER	

## 12. ELECTRICAL COMPONENTS AND LAYOUT




## 12. CONTROL PANEL, SWITCHES AND SYMBOLS



1. SWITCH
2. COOLANT PUMP SWITCH
3. PILOT LAMP
4. EMERGENCY STOP
5. JOGGING



# 13. POWER CIRCUIT



# 14. SCHEDULE OF ELECTRICAL EQUIPMENT

MANUFACTURER EXTRON		SCHEDULE OF ELECTRICAL			SHEET	
ORDER		EQUIPMENT				
TYPE				DRAWN		
LATHE MACHINE (18DF - "CE")				CHECKED		
ITEM DESIGNATION	DESCRIPTION AND FUNCTION	TECHNICAL DATA	QTY.	SUPPLIER	SUPPLIERS REFERENCE	REMARKS
QS	MAIN POWER (DOOR LOCK) SWITCH	AC 500V/50Hz 3P 16A	1	BULLETTIN	BULLETTIN 16942	IEC 529 IP 55
FU1	AC FUSE	AC 600V	1	SHINING	FS-012	CSA.C22.2
FU2	TO TRANSFORMER	30 mm 2A				NO.59.2
FU3	AC LOW VOLTAGE	AV 600V	1	SHINING	FS-011	CSA.C22.2
	TO TRANSFORMER	30 mm 3A				NO.59.2
KM1	CONTRACTORS	3PLA RI=AC 660V	1	N.H.D	C-09D10	IEC 292
KM2		RT= 25A	1	HUH-DIAN	(4A)	VDE 0660
KM3		AC3 220V 2.2KW	1			BS 5424-1
		380V 4.0KW				JIS 8325
FR	OVER-LOAD (RELAYS)	5 ~ 8A 6.5A UI=AC 600V ITH= 10A	1	N.H.D HUN-DIAN	BTH-12 (1NO+1NC)	IEC 292 VDE 0660 JIS 8325 BS 5424-1
KA	CONTRACTORS-RELAY	COIL=AC 24V AV 24V 5A DC 30V 5A	1	IDECIZUMI	RY4S-U	UL E55996 CSA LR25144
TC	TRANSFORMER	AC HI=380V(220V) LO=24V TR-72VA	1	SUENN-LIANG	SP-TBS	IEC 76-5 EN 60742 IEC IP-2
TB	CASSETTE TERMINAL-BLOCK	AC 600V MAX.15A	8	SHINING	TD-015H	UL E121562
PL	PILOT-LAMPS	AC 24V 1.5W 22	1	MACK	MK / L-22	IEC 144 IP 65
SB1	KEY-SWITCH	AC 250V 10A	1	MACK	MK / KS-22	IEC 144
SB2	EMERGENCY-STOP	MAX.500V	1	MOELLER		IP 65
SB3	JOGGING-BUTTON	380V 7.5A	1	MACK	MK / BF-22	
SB4	PUMP-SELECTOR	1NO+1NC 22	1	MACK	MK / C-22	
SQ1	SAFE-COVER (LIMIT SWITCH)	AC 400V 15.2A 380V 7.5A 1NO+ANC 22	1	ORMON	D4D-1520N	IEC 947-5-1 EN 60947-5-1 EN 50047 IP 65
SQ2	FOR-LIMIT.SWITCH-SQ5	AC 125V 10A	1	MOUJEN	MJ - 1704	UL E100182
SQ3	REV-LIMIT SWITCH-SQ6	250V 10A	1			UL 66C7
SQ4	FOOT-CUT(L.S)	DC 115V 0.4A	1			
SQ5	BAD WAY-CUT(L.S) - SQ2	MAX.600V	1			
CABLE-LOCK	CABLE - GLANDS		10	AVG	M - 16	IP 68
LINE	CONTROL - LINE	0.75 MAX.300V (30 / 0.18) - 7A AMBIENT TEMP (35°C ~ 60°C )	1	TONG - WU		CNS 679 JIS C3307
CABLE	PVC CABLE - WIRE	2.0 × 4C(37 / 0.26)16A 1.25 × 4(50 / 0.18) / 11A AMBIENT TEMP ( 35°C ~ 60°C ) MAX. 600V	1	TONG - WU		CNS 3301.4398 JIS C3342 3401
M1	MAIN - MOTOR		1			
M2	PUMP - MOTOR		1			

