




Insert the USB and boot your computer  
Press "DEL" and select the "Bios Setup Utility"  
Boot> Boot Disk Drives> 1<sup>st</sup> Drive> USB




## F10 Safe and Exit




Computer will boot automatically after "F10 Safe and Exit."

Computer then will show this (windows is loading files):



You will see:

- 1: New disk (create OS recovery with F10 hot-key recovery)
- 2: OS recovery. Only effective when Press 1 is done.
- 3: Exit
4. Reboot



**We have to Press 1 and wait for the recovery for about 5 mins.**  
*PS. Please do not remove the USB during the recovery. It may cause some damage to USB.*



Remove the USB after the reboot. If you forget to remove it, the screen will go back to the above window again. It's OK. Just Press 4 and remove the USB when you see the computer is ready to reboot.

The recovery is done.